



Enbridge Pipelines (Lakehead) L.L.C.  
119 N 25<sup>th</sup> Street E  
Superior, WI 54880  
[www.enbridgepartners.com](http://www.enbridgepartners.com)

Mark J. Willoughby, Manager  
Compliance  
Tel 715 394 1534  
Fax 715 394 1500  
[mark.willoughby@enbridge.com](mailto:mark.willoughby@enbridge.com)

MAR 23 2007

**Vector Pipeline™**

RECEIVED MAR 23 2007

March 19, 2007

Ivan A Huntoon  
Director, Central Region  
Office of Pipeline Safety  
901 Locust Street, Room 462E  
Kansas City MO 64106

Re: CPF 3-2007-1003W  
2005 Vector Records and Field Audit


Dear Mr. Huntoon:

Based on PHMSA's Field and Records inspection in October and November of 2005 of the Illinois and Indiana portion of Vector Pipeline, the following items were noted as requiring our attention.

In reference to Item (1) in CPF 3-2007-1003W Enbridge removed a coupon during the hot tap at the Crete Meter Station and did not have a documented Internal Inspection performed. A discussion was held with the Pipeline Maintenance Supervisor who performed the inspection but stated they neglected to complete the paperwork. Since that time a change was made to Enbridge's PLM Reporting System (software used to track all changes made to the Main Line) which requires documenting the inspection on an internal corrosion inspection report anytime the inside of the pipe is exposed. The PLM Reporting System asks a series of questions which will ensure that this form is completed in all applicable situations.

We trust these items have been addressed to your satisfaction. However, if you have any additional questions, please let me know. We appreciate the opportunity to work with PHMSA to correct any perceived deficiencies to ensure overall pipeline safety.

Sincerely,

  
Mark Willoughby

cc: Steve Irving  
Craig Fishbeck  
Tom Fridel  
Terrance McGill  
Leon Zupan